

- Drive
- Data
- Sensing
- LEDs
- Events
- Operators
- Sound
- Control
- Comment

turn line tracking LED on

turn obstacle detection beam on

clear clap detector sensor data

clap detected

round button pressed

obstacle detected anywhere

line tracker on reflective surface

remote code 0 received

IR message detected

drive strain detected

received IR message

light level of left light sensor

Start

turn line tracking LED on

forever

- turn forwards left until line tracker on non-reflective surface at speed 5
- turn forwards right until line tracker on reflective surface at speed 5